

## **CDM Post Operations Analysis 28.04.2025**

CDM for Date:	28/04/2025	CDM Name:	CDM5_VIDP_280425	Applicable Airport:	VIDP	Time (UTC):	1700-2100	
Reason:	RWY 10/28 ILS CAT3 UPGRADATION WIP & EASTERLY MODE OF OPERATIONS	Max. Delay (Mins.):	88	Average Delay (Mins.):	25	_		

ATFM MEASURES	CDM ANALYSIS  GDP1/GDP2/GDP3/GDP4							Flights Operated but Not Captured in CDM		
DURATION (From – To in UTC)	170	0-1800	1800-1900		1900-2000		2000-2100		SHIFTED TO NEXT HOUR (2100-2200)	
Predicted demand of Arrival (Skyflow)	Current	Carryforward (previous hrs)	Current	Carryforward (previous hrs)	Current	Carryforward (previous hrs)	Current	Carryforward (previous hrs)	04	
	60	00	35	20	25	29	16	21		
No. of Arrivals Planned for this Period	40		26		33		33			
Actual Arrivals (As per SKYFLOW)		38	33		27		28			
Manual CTOTs (Nos.)										27
Compliance (%)									100	
Accuracy (%)										94

**NOTE:** Accuracy of the CDM is the hourly callsign wise comparison between the predicted flights during preparation of CDM with flights actually operated. It is measured in percentage (%)

DETAILS OF CTOT NON-COMPLIANT FLIGHTS							
Call sign	ADEP	EOBT	стот	Revised EOBT	Revised manual CTOT	System ATOT	Reason for Non- Compliance (as reported by ATC)



Any Other Relevant Issues / Remark:

CTOT NON-COMPLIANCE SUMMARY							
Airp	port		Airline				
Airport Name	Total Number		Operator Name	Total Number			
CDM OBSERVATIONS / FEEDBACK							
Traffic Flow:	SMOOTH						
Substantial Holdings (>15 Mins.):	NIL						
Diversions (If Any):	NIL						
Any Unanticipated Events:	NIL						
Flight Data Issue:	NIL						
Airspace Data Issue:	NIL						
PRI Lines (Status):	SERVICEABLE (Outgoing Calls Only)						

TEAM-B	DHANRAJ MEENA, Jt.GM (ATM-ATFM)
Prepared by	Operations Shift Supervisor

CCC/CATFM/v3.0/28-04-2025 Page | 2