

**ATFM Post operations CDM Analysis 26.01.2020(Corrected)**

CDM for Date: 26.01.2020

CDM Name: CDM1_VIDP_260120

Applicable Airport: VIDP

Time (UTC): From 06:00 To 09:00

Reason: RWY CLOSURE DUE REPUBLIC DAY CELEBRATION Maximum Delay (Mins): 29 Mins Average Delay (Mins.): 03 Mins**A. CDM Analysis**

ATFM Measures	GDP 1	GDP 2	GDP 3		Overall CDM period
Duration	(Hourly Period) 0600 - 0700	(Hourly Period) 0700-0800	(Hourly Period) 0800-0900		
Predicted demand of Arrival (Skyflow)	40	51	30		
No of Arrivals Planned	23	40	32		
Actual Arrivals (as per Airport)	19	45	31		
Actual Arrivals (As per SKYFLOW)	19	45	34		
Manual CTOTs (Nos.)	--	--	--		15
Compliance (%)	--	--	--		92 %
Accuracy (%)	--	--	--		97 %

NOTE: Accuracy of the CDM is the hourly callsign wise comparison between the predicted flights during preparation of CDM with flights actually operated. It is measured in percentage (%)

**B. Details of CTOT Non-Compliance Flights:**

Call sign	ADEP	EOBT	ETOT	CTOT	Revised EOBT	Revised manual CTOT	System ATOT
LLR614	VIJU	0445	0455	0500	_____	_____	0617
IGO2902	VISR	0525	0535	0540	_____	_____	0627
AIC446	VILH	0625	0635	0652	_____	_____	0630
LLR814	VIGG	0510	0520	0520	_____	_____	0545
SEJ2732	VIAX	0610	0620	0649	_____	_____	0744

C. Summary of CTOT non-compliance:

CTOT non-compliant summary			
AIRPORT		AIRLINE	
AIRPORT NAME	TOTAL NUMBER	OPERATOR NAME	TOTAL NUMBER
VIJU	1	AIRINDIA	1
VISR	1	ALLIANCE AIR	2
VILH	1	SPICEJET	1
VIGG	1	INDIGO	1
VIAX	1		

**D. Observation / Feedback**

CDM Observations / Feedback	
TRAFFIC FLOW:	SMOOTH, NO HOLDING
SUBSTANTIAL HOLDINGS (>15 mins.):	NIL
DIVERSIONS (IF ANY):	NIL
ANY UNANTICIPATED EVENTS:	NIL
FLIGHT DATA ISSUE	NIL
AIRSPACE DATA ISSUE	NIL
ANY OTHER RELEVANT ISSUES / REMARK:	<ol style="list-style-type: none">1. Jt.GM(Ops) IGI airport agreed planning of arrivals from 0610 UTC.2. Clear weather at Delhi3. All pre closure period flights landed by 0519 UTC. ETH3749 ZSPD/VIDP was the last arrival before closure at 0519.4. Meteorological observer was present in CCC.5. CDM was applied at 03:28 UTC. No delay in dissemination of CTOTs.6. Very Few Non-compliance from ATC units/FMPs.7. Only one Airline representative was present in CCC i.e. from Indigo Airlines.8. First landing took place at 0610 (Air-force flight "Dornier") and first scheduled Arrival, GOW032 VTSP/VIDP, landed at 0626. Airport acceptance rate was planned to be 40. Maximum delay to Domestic flight was 29 minutes.9. International Flight Schedules for AIC333, UTP9943,AIC188, FDX5277, CKS250 etc. didn't operate.10. SEJ032 VHHH/VIDP FPL received but flight landed at Kolkata as planned by Spice jet operations. Mail to this effect received from Spice jet.11. AIC317 VHHH/VIDP FPL was discarded in SKYFLOW but the flight was observed to be operating.12. Traffic was observed to be smooth.

Team - C

(Prepared by)

VINAY ARORA
(Operation Shift Supervisor)