

CDM Post Operations Analysis 14.12.2022

CDM for Date: 14/12/2022 CDM Name: CDM1_VIDP_141222 Applicable Airport: VIDP Time (UTC): 0400 - 0700 UTC

Reason: NON-AVAILABILITY OF RWY 27 Max. Delay (Mins) 73 Average Delay (Mins.): 04

CDM ANALYSIS				Flights Operated But Not Captured in SKYFLOW	
ATFM MEASURES	GDP1	GDP2	GDP3		
DURATION (From – To in UTC)	0400 – 0500	0500 – 0600	0600 - 0700		
Predicted demand of Arrival (Skyflow)	52	38	40		
No. of Arrivals Planned for this Period	41	32	42		
Actual Arrivals (As per SKYFLOW)	35	43	26		
Manual CTOTs (Nos.)					02
Compliance (%)					94
Accuracy (%)					91

NOTE: Accuracy of the CDM is the hourly callsign wise comparison between the predicted flights during preparation of CDM with flights actually operated. It is measured in percentage (%)

DETAILS OF CTOT NON-COMPLIANT FLIGHTS							
Call sign	ADEP	EOBT	ETOT	стот	Revised EOBT	Revised manual CTOT	System ATOT
IGO2281	VILK	0505	0510	0543			0532
VTI786	VEBS	0410	0415	0445			0435
IGO2149	VEBD	0430	0435	0457			0437
IGO6821	VABB	0455	0500	0501			0529

CCC/CATFM/v3.0/14-12-2022 Page | 1



CTOT NON-COMPLIANCE SUMMARY					
Airport			Airline		
Airport Name	Total Number		Operator Name	Total Number	
VABB	01		INDIGO	03	
VEBD	01		VISTARA	01	
VEBS	01				
VILK	01				

CDM OBSERVATIONS / FEEDBACK		
Traffic Flow:	SLIGHT HOLDING BETWEEN 0400 – 0500 UTC	
Substantial Holdings (>15 Mins.):	NIL	
Diversions (If Any):	AIC914(OEDF-VIDP) DIVERTED TO VIJP	
Any Unanticipated Events:	NIL	
Flight Data Issue:	NIL	
Airspace Data Issue:	NIL	
Any Other Relevant Issues / Remark:	CDM WAS APPLIED DUE TO DRONE SIGHTING NEAR RWY 27	

TEAM- C

Prepared by (Officer's Sign., Name & Designation)

ASHWANI KUMAR, AGM(ATFM)

Operations Shift Supervisor (Sign., Name & Desig.)

CCC/CATFM/v3.0/14-12-2022 Page | 2